




MOTOR ASSEMBLY

USE OF WRONG PARTS MAY BE HAZARDOUS.

M-8001
Rev. 1/04



INSTRUCTIONS	COL. NO.
058541-001-000	1 & 2

NEW MODELS ADDED $\Rightarrow$ FIRST ISSUE	3/00	COLUMN #: 1, 2, 3, 4										
059780-200-000 MTR ASY, YELLOW,1503-02A	X											
059778-200-000 MTR ASY, SILVER ,1501-02A		X										
059780-100-000 MTR ASY, GRAY,1503-02A			X									
059778-100-000 MTR ASY, BLUE ,1501-02A				X								
WIRING DIAGRAM - SEE VIEW	1	2	1	2								
MODEL OR SERVICE NO. COLUMN $\rightarrow$	1	2	3	4	5	6	7	8	9	10	11	

[illegible]

NOTE 1

IF SERVICER HAS THE PROPER EQUIPMENT TO DISASSEMBLE & ASSEMBLE FRONT & REAR BEARINGS, THEY ARE AVAILABLE SEPARATELY. FAN MAY ALSO BE OBTAINED UPON REQUEST. CONTACT OSTER PRODUCT SERVICE FOR DETAILS.

MANUAL: STEWART

CONTINUED ON REVERSE SIDE

SECTION: CLIPPERS

PAGE: 123



150 CADILLAC LANE

McMINNVILLE, TN 37110

EXAMPLE:

28	29
30	30

THE COMPONENT PARTS (SMALL INDEX NO.'S)
ARE INCLUDED WHEN ORDERING
THE ASSEMBLY PART (LARGE INDEX NO.)

NOTE: NUMBERS SHOWN ON DRAWING
ARE INDEX NUMBERS ONLY, ORDER
PARTS BY CORRECT PART NUMBER.

